



İÇ DIŞ TİCARET VE SANAYİ A.Ş.

Date: 13/04/2016

To Whom It May Concern,

Protector DLP® Lightning Conductors are made of rust free and noncorrosive components. Besides, there is no battery or electronic component that can limit the lifespan of ESE lightning conductors. We can confirm that **Protector DLP®** Lightning Conductors are designed to serve at least 30 years on the condition that all the necessary controls are carried out. The life span is based upon the metallic restrin that is formed by severe discharge activities in various areas.

After the installation, it is advised that the system should be tested on annual basis. The ESE lightning conductor is to be tested with its original test device to confirm its correct operation. In order to maintain the proper function of the whole system, the installation (down conductor and fixings) and the earthing resistivity must also be checked regularly.


İÇ DIŞ TİCARET VE SANAYİ A.Ş.
Park Yaşam Ofis B32 Giriş D: 309
Karşıyaka / İZMİR
Tic. Sic. No: 269003447000016

Date: 13/04/2016



Onome kome može poslužiti,

Protector od DLP sistema gromobrana je napravljen od nerđajućih i nekorozivnih komponenti. Osim toga, nema bateriju ili elektronske komponente koje mogu da ograniče životni vek gromobrana ESE (uređaja za rano startovanje). Mi možemo potvrditi da je Protector projektovan da služi *najmanje 30 godina* pod uslovom da su sprovedene sve potrebne kontrole. Životni vek je zasnovan na ograničenjima metala formiranim jakim aktivnostima pražnjenja u različitim oblastima.

Nakon instalacije, savetuje se da sistem treba da bude testiran na godišnjem nivou. Gromobran sa uređajem za rano startovanje ESE bi trebalo da se proverava njegovim originalnim uređajem za testiranje, koji potvrđuje njegov ispravni rad. U cilju održavanja pravilnog funkcionisanja celog sistema, instalacija (donji provodnik i učvršćenje) i otpornost uzemljenja, takođe se moraju redovno proveravati.

Dameks Co.